IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

U.S. Patent No.: 7,582,204 B2`

Serial No. : 10/584,048

Filed : June 22, 2006

Issued: September 1, 2009

For : METHOD FOR TREATING A HYDROCARBON FEEDSTOCK INCLUDING

RESIN REMOVAL

PETITION FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 C.F.R. § 1.322 OR § 1.323

Commissioner for Patents P.O. Box 1450 Alexandria VA 22313-1450

Sir:

Applicants hereby request that the above-identified U.S. patent be corrected in accordance with the attached Certificate of Correction

I. C.F.R. § 1.322

The mistake(s) was incurred through the fault of the Patent and Trademark Office and is clearly disclosed in the records of the Office. Therefore, no fee is due.

II. C.F.R. § 1.323

At least some of the mistakes was/were made by the applicant. Therefore, a check in the amount of \$100.00 in payment of the fee set forth in 37 C.F.R. § 1.20(a) is enclosed herewith.

Enclosed herewith is a Form PTO-1050 (in duplicate) listing an error that has been found in the above-identified patent. The error(s) is of a clerical or typographical nature or of minor character and was made in good faith. The requested correction(s) does not constitute new matter or require reexamination.

III. Accordingly, patentees and their assignee respectfully request that the Patent and Trademark Office issue a Certificate of Correction pursuant to 37 C.F.R. § 1.322 or § 1.323, respectively.

Respectfully submitted,

/I. William Millen/

I. William Millen, Reg. No. 19,544 Attorney for Applicants

MILLEN, WHITE, ZELANO & BRANIGAN, P.C. Arlington Courthouse Plaza I 2200 Clarendon Blvd. Suite 1400 Arlington, Virginia 22201 Telephone: (703) 243-6333 Facsimile: (703) 243-6410

Attorney Docket No.: PET-2255

Date: September 17, 2009